

EBO

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Applicant: LIAOYANG BAILE HEALTH CARE PRODUCT CO., LTD.
Address: NO.160-1 liaoan Road, Liaoyang City, Liaoning Province, China
Manufacturer: LIAOYANG BAILE HEALTH CARE PRODUCT CO., LTD.
Address: NO.160-1 liaoan Road, Liaoyang City, Liaoning Province, China
EUT: MASSAGERS
Model No.: Please refer to next page.
Report No.: EBO2301091-C302


According to the reports submitted by the applicant, the results shown on the report do not exceed the limits as set by European RoHS Directive.

(EU) 2015/863 amending Annex II to Directive 2011/65/EU

The Verification is based on the reports which submitted by the applicant. The applicant should be responsible for the authenticity and validity of reports. Technical report and documentation are at the Holder's disposal. This Verification applies specifically to the sample investigated in our Integration report only. The CE mark as shown below can be used, under the responsibility of the manufacturer, after completion of an EC Declaration of Conformity and compliance with all relevant EC Directives.



Kevin Wang
Laboratory Manager



Issue Date: February 7, 2023

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BI-014905, BI-210209, BI-210179, BI-014563, BW-069004, BI-014320, BI-014731, BI-014732, BI-014563-1, BW-069004-1, BI-014324, BI-014722, BI-014733, BI-014560, BI-014601, BI-014711W, BI-014717, BI-014734, BI-014560-1, BI-014601-1, BI-014708, BI-014718, BI-014735, BI-014561, BI-014635, BI-014700W, BI-014719, BI-014736, BI-014561-1, BI-014635-1, BI-014654, BI-014720, BI-014737, BI-014547, BI-014580, BI-014609W, BI-014721, BI-014714, BI-014547-1, BI-014581, BI-014609W-1, BI-040078W, BI-014715BLT, BI-014547-4, BI-014588, BI-014653, BI-040076, BI-014681, BI-014547-3, BI-014584X, BI-014653-1, BI-210203, BI-014705, BI-014547-5, BI-014584X-1, BI-014656, BI-210204, BI-014706, BI-014547-6, BI-014533, BI-014656-1, BI-210205, BI-040077, BI-014547-7, BI-014571, BI-014647W, BI-210206, BI-014695, BI-014564, BI-014571-2, BI-014595W, BI-026235, BI-014696, BI-014564-1, BI-014571-1, BI-040073W, BI-026236, BI-014697, BI-014564-2, BI-014507, BI-040066W, BI-014707, BI-014693, BI-014738, BI-014507-2, BI-014548, BI-014716, BI-014701, BI-014739, BI-014507-1, BI-014548W, BI-014596, BI-014702, BI-014726, BI-014513, BW-008097X, BI-014597, BI-040067, BW-069006, BI-014513-1, BW-008087N, BI-014598, BI-040067-1, BI-014692, BI-014513-2, BW-008091N, BI-014599, BI-014663, BI-014727, BI-014534, BW-008092N, BW-012011, BI-014593, BI-014728, BI-014534-1, BW-008093N, BI-014648, BI-014593-1, BI-014729, BI-014534-2, BW-008094N, BI-014648-1, BI-014676, BI-040079W, BI-014542-2, BW-008072ZSY, BI-014661, BI-014676-1, BI-014730, BI-014542-1, BW-008073ZSY, BI-210200, BI-014640, BI-014723, BW-072001, BW-008074ZSY, BI-210192, BI-014640-1, BI-014724, BW-072005, BW-008041ZSY, BI-210198, BI-040069, BI-014725, BW-072006, BW-008017ARSY, BI-210199, BI-040069-1, BW-069005, BW-022056N, BW-008017BRSY, BI-014629, BI-014650, BI-014712, BW-037351-2, BM-00900T54S, BI-014630, BI-014650-1, BI-014713, BI-014473W-2, BM-00900T54S-1, BI-014631, BI-014650-2, BI-014709, BI-014578W, BM-00900T54, BI-014501, BI-014612, BI-014710, BI-210150, BM-00900T54-1, BI-014501-1, BI-014612-1, BI-014666, BI-210151, BM-009132U, BI-014605, BI-014613, BI-014667, BI-210190W, BM-009154U, BI-040065, BI-014613-1, BI-014694, BI-014576W, BM-009155U, BI-040065-1, BI-014610, BI-014668, BI-014577, BM-009156U, BI-040068, BI-014610-1, BI-014623, BI-014587, BM-009157U, BI-040068-1, BI-014611, BI-014624, BI-014465, BM-009158U, BI-014515, BI-014611-1, BI-014625, BI-014125

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BM-009215U, BI-014515-1, BI-014616, BI-014626, BI-014136, BM-009216U, BI-014505, BI-014616-1, BI-014633-1, BI-014145, BM-009217U, BI-026234, BI-014617, BI-014602, BI-014145-1, BM-009218U, BI-014539, BI-014617-1, BI-014622, BI-014147, BM-009219U, BI-014153-1, BI-014606, BI-014622-1, BI-014148, BM-009220U, BI-014541, BI-014606-1, BI-014651, BI-014171, BM-009221U, BI-014540, BI-014607, BI-014651-1, BI-014210, BW-022051, BI-210181, BI-014607-1, BI-014651-2, BI-014240, BW-022052, BI-210183, BI-014358-1, BI-014639, BI-014241, BW-022053, BI-210184, BI-014432-1, BI-014639-1, BI-014245, BM-009213Z, BI-210185, BI-014495-1, BI-014644, BI-014255, BM-010067APL, BI-210156, BI-067002-1, BI-014603, BI-014430, BM-010093PL, BI-210170, BI-067003-1, BW-069003, BI-014449, BM-010066D, BI-210169, BI-014313-2, BW-069003-1, BI-014032, BM-010066BPL, BI-210161, BI-014281-1, BI-014620, BI-014034, BM-010088PL, BI-210171, BI-014359-1, BI-014620-1, BI-014035, BI-210207, BI-210172, BI-014546, BI-014621, BI-014035A, BI-210208, BI-210174, BI-014546-1, BI-014621-1, BI-014046, BI-014057, BI-014058, BI-014072W, BI-014129HP, BI-014132, BI-014132-1, BI-014181, BI-014182, BI-014183, BI-014189, BI-014236, BI-014236-1, BI-014271, BI-014331, BI-014333, BI-014362, BI-014362W, BI-014368W, BI-014368W-3, BI-014369HP, BI-014370, BI-014374W, BI-014374W-1, BI-014377W, BI-014377W-1, BI-014403W, BI-014404W, BI-014405W, BI-014406W, BI-014415HP, BI-014415W, BI-014418W, BW-022045W, BI-014131, BI-014131-1, BI-014131-2, BI-014190, BI-014237, BI-014237-1, BI-040045W, BI-040052W, BI-014368-3, BI-040045, BI-040053, BI-014362W-9, BI-014447, BI-014466, BI-014482W, BI-014484W, BI-014485W, BI-014477W, BI-014477HP, BI-014478W, BI-014479W, BI-014487W, BI-014362W-3, BI-014362W-4, BI-014362W-5, BI-014362W-6, BI-014362W-10, BI-014362W-11, BI-014362W-13, BI-014525W-5, BI-014525-2, BI-014362HP-1, BI-014430W-1, BI-014519, BI-014500W, BI-014508W, BI-014582W, BI-014582HP, BI-014525, BI-014525-1, BI-014527, BI-014555, BI-014583W, BI-014584X, BI-014585, BI-014586, BI-014590, BI-014591, BI-014592, BI-014593, BI-014594W, BI-014595W, BI-014532, BI-014473W, BI-014525-3, BW-004001, BW-004101, BW-004102, BW-004103, BW-004104, BW-004105, BW-004106, BW-004107, BW-004108, BW-020001, BW-020001A, BW-020003, BW-020003A, BW-020004, BW-020004A, BW-020005, BW-020006, BW-020007, BW-020008, BW-020009, BW-020010, BW-020011

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BW-020012, BW-020014, BW-020024, BW-020025, BW-020027, BW-020031, BW-020032, BW-020033, BW-020236R, BW-020521R, BW-020525R, BW-020531R, BW-020534R, BW-020535R, BW-029523R, BW-029533R, BW-029534R, BW-033785, BW-037003, BW-037009, BW-037010, BW-037011, BW-037012, BW-037013, BW-037017, BW-037020, BW-037021, BW-037021A, BW-037022A, BW-037023, BW-037025, BW-037026, BW-037027, BW-037028, BW-037029, BW-037030, BW-037031, BW-037034, BW-037037, BW-037038, BW-037201, BW-037202, BW-037203J, BW-037251, BW-037252, BW-037301, BW-037302, BW-037302J, BW-037303, BW-037351, BW-037352, BW-037501, BW-037501J, BW-037502, BW-037551, BW-037552, BW-043001, BW-043005, BW-043006, BW-043007, BW-045001, BW-045002, BW-046201, BW-046202, BW-046203, BW-046431, BW-046432, BW-046433, BW-046434, BW-046435, BW-046451, BW-046452, BW-046453, BW-057001, BW-057002, BW-058001, BW-058002, BW-058003, BW-058005, BW-058006, BW-058007, BW-058008, BW-063001, BW-063003, BW-063004, BW-063008, BW-065005, BW-020536R, BW-037035, BW-037036, BW-037039, BW-062001, BW-062003, BW-062005, BW-063002, BW-037351-1, BW-008097X, BW-022050, BI-014530, BI-006078, BI-006079, BI-014111-2, BW-008078AQ, BW-008080X, BW-008081X, BW-020017, BW-020018, BW-020030, BW-037001A, BW-037014, BW-038001, BW-047002, BW-047003, BW-048001, BW-048002, BW-048003, BW-048004, BW-051003, BW-051009, BW-061009, BW-062002, BI-014186, BM-00900T27N, BM-00900T27N-1, BM-00900T27N-2, BM-00900T27Z, BM-00900T27Z-1, BM-00900T27Z-2, BM-00900T29Z, BM-00900T29Z-1, BM-00900T30Z, BM-00900T30Z-1, BM-00900T31Z, BM-00900T31Z-1, BM-00900T31Z-2, BM-00900T32, BM-00900T33, BM-00900T34, BM-00900T35, BM-009033, BM-010066, BM-010066A, BM-010066B, BM-010067, BM-010067A, BM-010088, BM-010092, BM-010093, BM-010095, BM-010096, BM-010099, BI-014091, BI-014091-1, BI-014091-2, BI-014091-3, BI-014091-5, BI-014091-6, BI-014091-7, BI-014096, BI-014096-1, BI-036019, BI-035012, BM-00900T36, BM-00900T37, BM-00900T38, BM-00900T46Z, BM-00900T46Z-1, BM-00900T46S, BM-00900T46S-1, BM-00900T46N, BM-900T46N-1, BM-00900T47Z, BM-00900T47Z-1, BM-00900T47Z-2, BM-00900T47S, BM-00900T47S-1, BM-00900T47S-2, BM-00900T47N, BM-00900T47N-1, BM-00900T47N-2

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BM-00900T43, BM-00900T48N, BM-00900T48N-1, BM-00900T48N-2, BM-00900T48Z, BM-00900T48Z-1, BM-00900T48Z-2, BM-00900T49, BM-00900T49-1, BM-00900T49-2, BM-00900T49-3, BM-00900T49N, BM-00900T49N-1, BM-00900T49N-2, BM-00900T49N-3, BM-00900T49NN, BM-00900T49NN-1, BM-00900T49NN-2, BM-00900T49NN-3, BM-00900T49NNJ, BM-00900T49NNJ-1, BM-00900T49NNJ-2, BM-00900T49NNJ-3, BM-00900T50, BM-00900T50-1, BM-00900T50-2, BM-00900T50-3, BM-00900T52N, BI-010125R, BI-014091-8, BI-014096-2, BM-009150H, BM-009154H, BM-009023Z-1, BM-009107Z-1, BM-009113Z-1, BM-009115Z-1, BM-009022Z-1, BM-009039Z-1, BM-009190Z-1, BM-009141Z-1, BM-009173Z-1, BM-009175Z-1, BM-009131Z-1, BM-009194K, BM-009196K, BM-009198ZK, BM-009199ZK, BM-009200K, BM-009201K, BM-009202K, BM-009205K, BM-009206K, BM-009207K, BM-009208K, BM-009209K, BM-009210K, BM-009211K, BM-009212K, BM-009204Z-1, BM-00900T45, BM-00900T45-1, BI-014107, BI-014107-1, BI-014107-2, BI-014109, BI-014109-1, BI-014123, BI-014123-1, BI-014139, BI-014140, BI-014140-1, BI-014141, BI-014168, BI-014169, BI-014170, BI-014175, BI-014176, BI-014177, BI-014178, BI-014179, BI-014180, BI-014212, BI-014225, BI-014226, BI-014227, BI-014228, BI-014231, BI-014232, BI-014235, BI-014251, BI-014252, BI-014253, BI-014307, BI-014308, BI-014309, BI-014399, BI-014412, BI-014413, BI-014420, BI-069001, BI-069002, BW-037032, BW-037033, BW-052001-1, BW-052002-1, BW-052003-1, BW-052004-1, BW-053001, BW-053002, BW-053003, BW-055001, BW-055002, BW-055002A, BW-055003, BW-055003-1, BW-055009-1, BW-055009-2, BW-055010, BW-055011, BW-063005, BW-063009, BW-067001, BW-067002, BW-067003, BW-068002, BI-014433, BI-014231-1, BI-014232-1, BI-014442, BI-014443, BI-014443-1, BI-014467, BI-014467-1, BI-014468, BI-014468-1, BI-014455, BI-014453, BI-014475, BI-014480, BI-014495, BW-072001, BW-072002, BW-072003, BW-072004, BW-072005, BW-072006, BI-014572, BI-014571, BI-014507, BI-014513, BI-014534, BI-014542, BI-014533, BI-014580, BI-014581, BI-014588, BI-014601, BI-014602, BI-014603, BW-069003, MC02, MC03, MC04, MC06, MC07, MC08, MC16, MC16-1, MC17, MC17-1, MC18, MC18-1, MC19, MC21, MC22, MC25, MC-15, MC27, LKS205, LKS206, MC29, MC31, BI-010081, BI-010081A, BI-010082, BI-010082A, BI-010083, BI-010083A, BI-010084, BI-010084A, BI-010132-1, BI-010133-1, BI-010148

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BI-014075, BI-014076, BI-014078, BI-014079, BI-014080, BI-014081, BI-014102, BI-014103, BI-026043, BI-026200, BI-026201, BI-026201A, BI-026202, BI-026202A, BI-026203, BI-026203A, BI-026204, BI-026205, BI-026206, BI-026207, BI-026208, BI-026206-1, BI-026212, BI-026213, BI-026227, BI-026228, BI-210136, BI-210137, BI-014355, BI-210135, BI-210138, BI-210149, BI-26209, BI-26210, BI-26211, BI-26210A, BI-210140, BI-210141, BI-210142, BI-210147, BI-026215, BI-026215-1, BI-026216, BI-026216-1, BI-026218, BI-026219, BI-026220, BI-014438, BI-014437, BI-014408, BI-014409, BI-014410, BI-026223A-1, BI-026223, BI-026225A, BI-026225-1, BI-010132-2, BI-010133-2, BI-014075-1, BI-014079-1, BI-014080-1, BI-014081-1, BI-026216A, BI-040040, BI-040036, BI-040038, BI-040039, BI-014488, BI-0210152, BI-0210152HP, BI-014502, BI-014503, BI-014510, BI-014535, BI-026231, BI-026233, BI-026232, BI-210162W, BI-014545, BI-210156, BI-210170, BI-210169, BI-210164, BI-014153, BI-014153-1, BI-026234, BI-014539, BI-014548, BI-014548W, BI-014515, BI-210178, BI-014596, BI-014597, BI-014598, BI-014599, BI-014600H, BI-210163W, BI-010104A, BI-014037, BI-014049-6, BI-014112, BI-014127, BI-014137, BI-014138, BI-014142, BI-014143, BI-014144, BI-014146, BI-014152, BI-036012, BI-040006, BI-040007, BI-040017, BI-040025, BI-040027, BI-014161, BI-014100, BI-014100-1, BI-014108, BI-014108-1, BI-014108-2, BI-014108-3, BI-014116, BI-014129, , BI-014155, BI-014172, BI-014173, BI-014173-1, BI-014173-2, BI-014174, BI-014187, BI-014188, BI-014191, BI-014192, BI-014193, BI-014194, BI-014200, BI-014201, BI-014202, BI-014208, BI-014216, BI-014217, BI-014218, BI-014218-1, BI-014219, BI-014220, BI-014221, BI-014222, BI-014223, BI-014224, BI-014242, BI-014243, BI-014244, BI-014263, BI-014264, BI-014277, BI-014277-1, BI-014278, BI-014278-1, BI-014279, BI-014279-1, BI-014281, BI-014282, BI-014283, BI-014284, BI-014285, BI-014287, BI-014288, BI-014289, BI-014291, BI-014292, BI-014293, BI-014299, BI-014305, BI-014306, BI-014312, BI-014313, BI-014313-1, BI-014316, BI-014317, BI-014320, BI-014327, BI-014327-1, BI-014327-2, BI-014327-3, BI-014327-5, BI-014327-6, BI-014329, BI-014330, BI-014332, BI-014335, BI-014339, BI-014340, BI-014341, BI-014346, BI-014347, BI-014356, BI-014357, BI-014358, BI-014359, BI-014360, BI-014368, BI-014386, BI-014387, BI-014388, BI-014422, BI-040028, BI-040029, BI-040031, BI-040032, BW-022045, BW-065001, BW-241016, BW-241017, BW-241020, BW-241025, BW-241028, BI-014111-2C, BI-014432

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BI-014463, BI-014527, BI-040059, BI-014546, BI-014563, BI-014560, BI-014561, BI-014547, BI-014275, BI-014564, BI-014567, BI-014543, BI-014577, BI-014587, BI-014552, BI-014575, BI-014699, BI-014594, BI-014691W, BI-014690W, BI-014699WBLT, BI-014415W-3BLT, BI-014415W-4BLT, BI-014415W-5BLT, BI-014715WBLT, BI-014236-2BLT, BI-014664, BI-014716WBLT, BW-072007, BW-072010, BW-072011, BI-014744W, BI-014756, BI-040079W-MR, BI-210210, BI-014716WBLT, BI-014236-2BLT, BI-014699WBLT, BI-014742, BI-014744W, BI-040063-1, BW-072007, BW-072010, BW-072011, BW-022060, BI-014749, BI-014750, BI-014751, BI-014752, BI-014753, BI-014754, BW-008098DAQ-MR, BW-008098Q-MR, BI-210211, BI-040081W, BI-040082, BI-014759W, BI-040083W, BW-008101, BW-008102N, BI-210213, BI-210214, BM-00900T56, BM-00900T57, BI-210212HP, BI-014731HP, BI-014732, BI-014734W, BI-014733, BI-014733W, BI-014735, BI-040076W-MR, BM-00900T58, BM-00900T59, BI-210216, BI-040083HP, BI-014733HP, BI-014609HP, BI-014647HP, BI-040084, BI-014652, BI-210197, BW-010025, BW-010026, BW-010058, BI-040074, BI-014690W, BI-014699, BI-014691W, BM-00900T55-1, BM-00900T55-2, BM-00900T55-3, BI-014665, BW-066005, BI-014362-9HP, BI-014473W-3, BI-014500HP, BI-014526, BI-014527HP, BI-014547-MR, BI-014653HP, BI-014654HP, BI-014668-1, BI-014708HP, BI-014737WBLT, BI-014738-1, BI-014755, BI-014758, BI-014761, BI-014762, BI-014763, BI-014764, BI-014765, BI-014765HP, BI-014766, BI-014767, BI-014768, BI-014772, BI-014773, BI-014774, BI-014775, BI-014781, BI-014782, BI-014783, BI-014784, BI-014785H, BI-014786, BI-014787, BI-014788, BI-014789, BI-014790, BI-014791, BI-014792, BI-014793, BI-014794, BI-014795, BI-014796, BI-014797, BI-026237, BI-040045W-MR, BI-040053-MR, BI-040066W-MR, BI-040080, BI-040080HP, BI-040082-MR, BI-040085W-MR, BI-040086W-MR, BI-040088, BI-040089, BI-040090, BI-040091, BI-040092, BI-040093, BI-040096Q, BI-210214-MR, BI-210217, BI-210218, BI-210219, BI-210220, BI-210221, BI-210222, BI-210223, BM-00900T60, BM-00900T61, BM-00900T62, BM-00900T63, BM-00900T64, BM-00900T65, BM-00900T66, BM-00900T67, BM-00900T68, BM-00900T69, BM-00900T70, BM-00900T71, BM-00900T72, BM-009222, BM-009223, BM-009224N, BM-009225, BM-009226, BM-009227, BM-009228, BM-009229, BM-009230, BM-009231, BM-009232, BM-009233, BM-009234, BM-009235, BM-009236

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BM-009237, BM-009238, BM-009239, BM-009240, BM-009241, BM-009242, BM-009243, BM-009244, BM-009245, BM-009246, BM-009247, BM-009248, BM-009249, BM-009250, BM-009251, BM-009252, BM-009253, BM-009254, BM-009255, BM-009256, BM-009257, BM-009258, BM-009259, BW-008103, BW-008104, BW-008105, BW-008106, BW-008107, BW-008108, BW-008109, BW-008110, BW-022061, BW-022062, BW-022063, BW-022064, BW-022065, BW-055012, JW-001, Z010, BI-014824W, BI-014825W, BI-014826W, BI-014827W, BI-014831W, BI-014833W, BI-014834W, BI-014463W, BI-014803W, BI-014813W, BW-022062W, BW-022063W, BW-022064W, BW-022065W, BW-022066W, BI-014843W, BI-014849W, BI-014850W, BI-014852W, BI-014853H, BI-014862W, BI-014865W, BI-014866LR, BI-014867W, BI-014868W, BI-014869W, BI-014872W, BW-001001R, BW-001004R, BW-001009R, BW-001032R, BW-001023R, BW-001071R, BW-001072R, BW-007013R, BW-008055R, BW-008015R, BW-008018BR, BW-008054R, BW-008101S, BW-008101N, BW-008037, BW-008038, BW-008039, BW-008040, BW-008041, BW-022064Z, BW-022066Z, BW-012006, BW-012008, BW-012009, BW-012010, BW-012011, BI-014832-1, BI-014832-2, BI-014832-3, BI-014832H, BW-007039R, BW-007037R, BI-014832-1, BI-014832-2, BI-014832-3, BI-014832H, BW-055013, BW-055014, MC27, MC33, MC34, MC35, MC36, MC37, MC38, MC39, MC40, BI-014776, BI-014777, BI-014805, BI-014880, BI-014881, BI-014882, BI-014883, BI-014884, BI-014807, BI-014808, BI-014823H, BI-014846H, BI-014847H, BI-014822, BI-014838, BI-014839, BI-014840, BI-014841, BI-014842, BI-014843, BI-014845, BI-040100, BI-040101, BI-040102, BI-040103, BI-040104, BI-040105, BI-040106, BI-040107, BI-040108, BI-014852, BI-014853H, BI-026225Z, BI-210236, BI-210237, BI-210238, BI-210239, BI-210240, BI-210241, BI-210242, BI-210243, BI-210244, BI-210245, BI-210246, BI-210247, BI-210248, BI-210249, BI-210250, BI-210251, BI-210252, BI-210234, BI-210235, BI-210236, BI-210237, BI-210238, BI-210239, BI-210240, BI-210241, BI-210225, BW-012011, BW-012012, BW-012013, BW-012014, BW-012015, BW-012016, BW-012017, BI-014818, BI-014844, BI-014851, BI-014836, BI-014855, BI-014858, BI-014859, BI-014860, BI-014861, BI-014862, BI-014863, BI-014864, BI-014865, BI-014866, BI-014867, BI-014868, BI-014869, BI-014870, BI-014871, BI-014872, BI-014873, BI-014874, BI-014875, BI-014876, BI-014877, BI-014877H, BI-014878, BI-014879, BI-014880

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BI-014881, BI-014882, BI-014883, BI-014884, BI-014885, BI-014886, BI-014887, BI-014888, BI-014889, BI-014890, BI-026237, BI-026238, BI-026239, BI-026240, BI-026241, BI-026242, BI-026243, BI-026244, BI-026245, BI-026246, BI-026247, BI-026248, BI-026249, BI-026250, BM-00900T73, BM-00900T74, BM-00900T75, BM-00900T76, BM-00900T77, BM-00900T78, BM-00900T79, BM-00900T80, BM-00900T81, BM-00900T82, BM-00900T83, BM-00900T84, BM-00900T85, BM-00900T86, BM-00900T87, BM-00900T88, BM-00900T89, BM-00900T90, BM-00900T91, BM-00900T92, BM-00900T93, BM-00900T94, BM-00900T95, BM-00900T96, BM-00900T97, BM-00900T98, BM-00900T99, BM-00900T100, BM-00900T101, BM-00900T102, BM-00900T103, BM-00900T104, BM-00900T105, BM-00900T106, BW-072012, BW-072013, BW-072014, BW-072015, BW-072016, BW-072017, BW-072018, BI-014848, BI-040116, BI-022080, BI-022081, BI-022082, BI-022083, BI-022084, BI-022085, BI-014891, BI-014892, BI-014893, BI-014894, BI-014895, BI-014902, BI-014925, BI-210257, BI-210275, BI-210276, BI-210277, BI-210278, BI-210279, BI-210280, BI-210281, BI-210282, BI-210283, BI-210284, BI-210285, BI-210286, BI-210287, BI-210288, BI-210289, BI-210290, BI-210291, BI-210292, BI-210293, BI-014915, BI-014927, BI-014934, BI-014935, BI-014936, BI-014937, BI-014938, BI-014939, BI-014940, BI-014941, BI-014942, BI-014943, BI-014944, BI-014945, BI-014946H, BI-014947, BI-014948, BI-014949, BI-014950, BI-014951, BI-014952, BI-014953, BI-014954, BI-014955, BI-014956, BI-014957, BI-014958, BI-014854, BI-040111, BI-021264, BI-014916, BI-040123, BI-040124, BI-040125, BI-040126, BI-040127C, BI-040128, BI-040129, BI-040130, BI-040131, BI-040132, BI-026245, BI-026246, BI-026247, BI-026248, BI-026249, BI-026250, BI-026251, BI-026252, BI-026253, BI-026254, BI-026255, BI-026256, BI-026257, BI-026258, BI-026259, BI-026260, BI-026261, BI-026262, BI-026263, BI-026264, BI-026265, BI-026266, BI-026267, BI-026268, BI-026269, BI-026270, BI-026271, BI-026272, BI-026273, BI-026274, BI-026275, BI-014910W, BI-014911HP, BW-022070ZW, BW-022071ZW, BW-022072ZW, BI-040133MR, BI-014970W, BI-04974HP, BI-040132W, BI-014992HP, BI-040148W, BW-022067P, BI-014961R, BI-014962R, BM-00900T27Z-3, BM-00900T27Z-4, BM-00900T27Z-5, BM-00900T27Z-6, BW-055015-LED, BW-055016, BW-055016-LED, BW-055017, BW-055018, BW-055019, BW-022087, BW-022093, BW-022073Z, BW-022074

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com

VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BI-014924, BI-014950-1, BI-014950-2, BI-014950-3, BI-014950-4, BI-014950-5,
BI-014976, BI-014978, BI-014979, BI-014980, BI-014981, BI-014982, BI-014983,
BI-014984, BI-014985, BI-014986, BI-014987, BI-014988, BI-014989, BI-014990,
BI-014991, BI-014992, BI-014993, BI-014994, BI-014995H, BI-014996, BI-014997,
BI-014998, BI-040134, BI-040135, BI-040136, BI-040137, BI-040141, BI-040142,
BI-040143, BI-040144, BI-040145, BI-040146, BI-040147, BI-040148, BI-040149,
BI-040150, BI-040151, BI-040152, BI-014987, BI-014963, BI-210294, BI-210295,
BI-210296, BI-210297, BI-210298, BI-210299, BI-210305, BI-210306, BI-210307,
BI-210308, BI-210309, BI-210310, BI-210311, BI-210312, BI-210313, BI-210314,
BI-210315, BI-210316, BI-210317, BI-210318, BI-210319, BI-210320, BI-210321,
BI-210322, BI-210323, BI-210324, BI-210325, BI-210326, BI-210327, BI-210328,
BI-210329, BI-210330, BI-210331, BI-300001, BI-300002, BI-300003, BI-300004,
BI-300005, BI-300006, BI-300007, BI-300008, BI-300009, BI-300010, BI-300011,
BI-300012, BI-300013, BI-300014, BI-300015, BI-300016, BI-300017, BI-300018,
BI-300019, BI-300020, BI-300021, BI-300022, BI-300023, BI-300024, BI-300025,
BI-300026, BI-300027, BI-300028, BI-300029, BI-300030, BI-300031, BI-300032,
BI-300033, BI-300034, BI-300035, BI-300036, BI-300037, BI-300038, BI-300039,
BI-300040, BI-300041, BI-300042, BI-300043, BI-300044, BI-300045, BI-300046,
BI-300047, BI-300048, BI-300049, BI-300050, BI-300051, BI-300052, BI-300053,
BI-300054, BI-300055, BI-300056, BI-300057, BI-300058, BI-300059, BI-300060,
BI-300061, BI-300062, BI-300063, BI-300064, BI-300065, BI-300066, BI-300067,
BI-300068, BI-300069, BI-300070, BI-300071, BI-300072, BI-300073, BI-300074,
BI-300075, BI-300076, BI-300077, BI-300078, BI-300079, BI-300080, BI-300081,
BI-300082, BI-300083, BI-300084, BI-300085, BI-300086, BI-300087, BI-300088,
BI-300089, BI-300090, BI-300091, BI-300092, BI-300093, BI-300094, BI-300095,
BI-300096, BI-300097, BI-300098, BI-300099, BI-300100, BI-300101, BI-300102,
BI-300103, BI-300104, BI-300105, BI-300106, BI-300107, BI-300108, BI-300109,
BI-300110, BI-300111, BI-300112, BI-300113, BI-300114, BI-300115, BI-300116,
BI-300117, BI-300118, BI-300119, BI-300120, BI-300121, BI-300122, BI-300123,
BI-300124, BI-300125, BI-300126, BI-300127, BI-300128, BI-300129, BI-300130,
BI-300131, BI-300132, BI-300133, BI-300134, BI-300135, BI-300136, BI-300137,
BI-300138, BI-300139, BI-300140, BI-300141, BI-300142, BI-300143, BI-300144,
BI-300145, BI-300146, BI-300147, BI-300148, BI-300149, BI-300150, BW-500001

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com



VERIFICATION OF COMPLIANCE

RoHS

No.: EBO2301091-V303

Model No.:

BW-500002, BW-500003, BW-500004, BW-500005, BW-500006, BW-500007, BW-500008, BW-500009, BW-500010, BW-500011, BW-500012, BW-500013, BW-500014, BW-500015, BW-500016, BW-500017, BW-500018, BW-500019, BW-500020, BW-500021, BW-500022, BW-500023, BW-500024, BW-500025, BW-500026, BW-500027, BW-500028, BW-500029, BW-500030, BW-500031, BW-500032, BW-500033, BW-500034, BW-500035, BW-500036, BW-500037, BW-500038, BW-500039, BW-500040, BW-500041, BW-500042, BW-500043, BW-500044, BW-500045, BW-500046, BW-500047, BW-500048, BW-500049, BW-500050, BW-500051, BW-500052, BW-500053, BW-500054, BW-500055, BW-500056, BW-500057, BW-500058, BW-500059, BW-500060, BW-500061, BW-500062, BW-500063, BW-500064, BW-500065, BW-500066, BW-500067, BW-500068, BW-500069, BW-500070, BW-500071, BW-500072, BW-500073, BW-500074, BW-500075, BW-500076, BW-500077, BW-500078, BW-500079, BW-500080, BW-500081, BW-500082, BW-500083, BW-500084, BW-500085, BW-500086, BW-500087, BW-500088, BW-500089, BW-500090, BW-500091, BW-500092, BW-500093, BW-500094, BW-500095, BW-500096, BW-500097, BW-500098, BW-500099, BW-500100, BW-500101, BW-500102, BW-500103, BW-500104, BW-500105, BW-500106, BW-500107, BW-500108, BW-500109, BW-500110, BW-500111, BW-500112, BW-500113, BW-500114, BW-500115, BW-500116, BW-500117, BW-500118, BW-500119, BW-500120, BW-500121, BW-500122, BW-500123, BW-500124, BW-500125, BW-500126, BW-500127, BW-500128, BW-500129, BW-500130, BW-500131, BW-500132, BW-500133, BW-500134, BW-500135, BW-500136, BW-500137, BW-500138, BW-500139, BW-500140, BW-500141, BW-500142, BW-500143, BW-500144, BW-500145, BW-500146, BW-500147, BW-500148, BW-500149, BW-500150, BW-500151, BW-500152, BW-500153, BW-500154, BW-500155, BW-500156, BW-500157, BW-500158, BW-500159, BW-500160, BW-500161, BW-500162, BW-500163, BW-500164, BW-500165, BW-500166, BW-500167, BW-500168, BW-500169, BW-500170, BW-500171, BW-500172, BW-500173, BW-500174, BW-500175, BW-500176, BW-500177, BW-500178, BW-500179, BW-500180, BW-500181, BW-500182, BW-500183, BW-500184, BW-500185, BW-500186, BW-500187, BW-500188, BW-500189, BW-500190, BW-500191, BW-500192, BW-500193, BW-500194, BW-500195, BW-500196, BW-500197, BW-500198, BW-500199, BW-500200

Shenzhen EBO Testing Center

2F, Qiaohongsheng Cultural Creative Park, Yintian Industrial Zone, Xixiang Street, Bao'an District, Shenzhen
Tel: 86-755-33126608 ebo@ebotest.com www.ebotest.com